EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1	(lap adj weld\$4) with weld\$4 near5 pattern with (spiral\$4 circ\$5 oval\$4 (back with forth) around)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/05/15 11:18
S2	1	(lap adj weld\$4) and weld\$4 and pattern and (spiral\$4 circ\$5 oval\$4 (back with forth) around)	JPO	OR	ON	2006/05/15 10:29
S3	17685	b23k026\$.ipc.	JPO	OR	ON	2006/05/15 10:29
S4	1	S2 and S3	JPO	OR	ON	2006/05/15 10:29
S5	15	S3 and weld\$4 and pattern and (spiral\$4 circ\$5 oval\$4 (back with forth) around)	JPO	OR	ON	2006/11/27 09:38
S6	6	((flange\$ lap\$4) adj weld\$4) with ((weld\$4 beam arc join\$3) with pattern\$3 with (spiral\$4 circ\$5 oval\$4 (back with forth) around))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 10:43
S7	2599	219/121.63,121.64.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 11:17
S8	1	S6 and S7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 11:17
S9 .	1	S1 and S7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 11:17
S10		S7 and weld\$4 near5 pattern with (spiral\$4 circ\$5 oval\$4 (back with forth) around)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 11:18
S11	3	laser with (long adj focus) with mirror	JPO	OR	ON	2006/11/27 09:38
S12	2	((flange\$ lap\$4 plate sheet\$6) near3 weld\$4) with (pattern\$3 with (spiral\$4 circ\$5 oval\$4 (back with forth) around)) with stress\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 10:49

EAST Search History

S13	2	((flange\$ lap\$4 plate sheet\$6) near3 weld\$4) with (pattern\$3 near3 (spiral\$4 circ\$5 oval\$4 (back with forth) around)) with stress\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 10:48
S14	3	((flange\$ lap\$4 plate sheet\$6) near5 weld\$4) same (pattern\$3 near5 (spiral\$4 circ\$5 oval\$4 (back with forth) around)) with stress\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 10:48
S15	1	S14 not S12	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 10:48
S16	92	((flange\$ lap\$4 plate sheet\$6) near3 weld\$4) with (weld\$3 with (spiral\$4 circ\$5 oval\$4 (back with forth) around)) with stress\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/07/11 10:49
S17	131	((flange\$ lap\$4 plate sheet\$6) near3 weld\$4) same (weld\$3 with (spiral\$4 circ\$5 oval\$4 (back with forth) around)) with stress\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 11:07
S18	44	(metal\$4 with (flange\$ lap\$4 plate sheet\$6) near3 weld\$4) same (weld\$3 with (spiral\$4 circ\$5 oval\$4 (back with forth) around)) with (stress\$4 crack\$4 ruptur\$4 fractur\$4 break\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/07/11 12:07